
Attachment 2

Photos:



Building #1: Hay barn altered to include dwelling unit. Unknown fire separations.




Building #1: Back entrance.



Building #2: First tack shed converted to a dwelling.



Building #3: Second tack shed converted to a dwelling.



Building #4: Horse barn. Top floor converted to a dwelling with lower floor storage. Inadequate fire separations.



Building #5: Tractor shed. Tractor storage area eliminated. Currently vacant.



Building #6: Washroom building. Alterations to interior, converting to a dwelling.



Building #7: Third tack shed converted to a dwelling.