



Making a difference...together

**REPORT TO ELECTORAL AREAS COMMITTEE
MEETING OF WEDNESDAY, JULY 8, 2020**

SUBJECT **File Notice on the Land Title of 510 Linklater Road, Lot 10, Block 2, District Lot 6, Galiano Island, Cowichan District, Plan 24167, PID 002-979-845, File NT000273**

ISSUE SUMMARY

The purpose of this staff report is to recommend that a notice be placed on the land title of the property described above as a result of non-compliance with Capital Regional District (CRD) or other regulations.

BACKGROUND

Since May 8, 2019, CRD Building Inspection staff has attempted to persuade the owner to comply with Building Regulation Bylaw No. 3741 (see Appendix A-History).

A Stop Work Order was posted on May 8, 2019 on a bathhouse structure constructed without the benefit of a building permit or approvals. Registered letters were sent requesting a building permit application be submitted.

A site visit on October 15, 2019 revealed the construction of the bathhouse structure had resumed and appeared to be completed. Although an extension was given to the owner to comply, a building permit application was not received.

The owner has been advised of the outstanding issues and requirements for compliance to the BC Building Code. The owner of the property violated the following sections of the Bylaw:

2.1.2 Permits Required

Every person shall apply for and obtain a building permit before commencing construction, repairing or altering a building or structure.

3.1.1 Work Without Permits

No person shall commence or continue any construction, alteration, reconstruction, demolition, removal or relocation of any building or structure or other work related to construction unless a building official has issued a valid and subsisting permit for the work.

3.1.3 Occupancy

No person shall occupy or use any building or structure unless a valid and subsisting Certificate of Occupancy has been issued by a building official for the building or structure. No person shall occupy or use any building contrary to the terms of any Permit issued or contrary to any notice given by a building official.

3.1.8 Contrary

No person shall do any work or carry out any construction contrary to a provision or requirement of the Bylaw, the *Building Code* or any other applicable enactment.

ALTERNATIVES

Alternative 1

That the Corporate Officer file a notice in the Victoria Land Title office stating that a Resolution has been made under Section 57 of the *Community Charter* relating to land legally described as: Lot 10, Block 2, District Lot 6, Galiano Island, Cowichan District, Plan 24167, PID 002-979-845 or any subdivision of said lands as may be affected by the contravention(s).

Alternative 2

That a notice not be filed and staff be directed to take no further action.

IMPLICATIONS

Financial

The cost of the process to file notice on land title is included in the annual Building Inspection budget. In the event that the notice can be removed, there will be a \$500 removal fee charged to the owner.

Legal

If a notice is not filed on the land title, the liability of the CRD is potentially increased and possible future owners may not be advised of a building inspection deficiency and may be exposed to potential loss. If CRD Bylaw Services is unable to achieve compliance, staff will bring forward a recommendation to proceed with legal action as required.

CONCLUSION

The Chief Building Inspector recommends placing notice on the land title to notify potential buyers of building deficiencies, the concerns of the CRD Building Inspector, and to reduce the liability of the CRD. Due to work carried out prior to inspection, it may be necessary to have the notice remain on title in perpetuity, as complete inspection of the work may not be possible.

RECOMMENDATION

That the Corporate Officer file a Notice in the Victoria Land Title office stating that a Resolution has been made under Section 57 of the *Community Charter* relating to land legally described as: Lot 10, Block 2, District Lot 6, Galiano Island, Cowichan District, Plan 24167, PID 002-979-845 or any subdivision of said lands as may be affected by the contravention(s).

Submitted by:	Mike Taylor, RBO, Manager and Chief Building Inspector, Building Inspection
Concurrence:	Kevin Lorette, P.Eng., MBA, General Manager, Planning & Protective Services

ATTACHMENTS

Appendix A: History
Appendix B: Photos