Capital Regional District

Legislation Details (With Text)

File #:	17-6	82	Version:	1	Name:	Req't Remedial Action - 1178 A	spen Road	
Туре:	Actio	on Report			Status:	Reported to Board		
File created:	9/15	6/2017			In control:	Capital Regional District Board		
On agenda:	9/20)/2017			Final action:	10/11/2017		
Title:	Request for Approval to Commence Remedial Action at 1178 Aspen Road, PID 000-256-382, Lot 2, District Lots 45 and 136, Malahat District, Plan 33710, File VF000205							
Sponsors:								
Indexes:								
Code sections:								
Attachments:	B: P	1. Staff Report: Request for Remedial Action - 1178 Aspen Road, 2. Appendix A: History, 3. Appendix B: Photos, 4. Appendix C: Div 12/Part 3, Sec 73 & 74 - Community Charter, 5. Letter to Property Owner re 1178 Aspen Rd VF000205 Remedial Action						
Date	Ver.	Action By			Ac	tion	Result	
10/11/2017	1	Capital F	Regional Dis	strict I	Board			
9/20/2017	1		Session Ele Committee		Area re	commended for approval	Pass	
Request for A	pprov	al to Co	mmence	Rem	edial Action a	t 1178 Aspen Road, PID 000)-256-382, Lot 2,	

District Lots 45 and 136, Malahat District, Plan 33710, File VF000205

That an Order to demolish the structure and remove all debris from the property at 1178 Aspen Road on lands legally described as Lot 2, District Lots 45 and 136, Malahat District Plan 33710, PID 000-256-382 to address the hazardous condition and nuisance structure to bring the property into compliance with the Provincial Building Regulation and Bylaw under Division 2 of Part 21 of the *Local Government Act and* CRD Regulation Bylaw No. 5, 2010 (Bylaw 3741) be imposed. (NWA)